Page: C

CL/SfB (43)

Hy-Glaze[™]WD

Industrial water dispersed epoxy interior wall coating



"maintenance made easy"



PRODUCT DESCRIPTION

Hy-Glaze[™] WD is a self-priming non-toxic two part waterdispersed epoxy resin wall coating with a high solid content of 54%. The formulation includes high build fillers to increase the film thickness and provide good abrasion and chemical resistance. Hy-Glaze[™] WD provides a dustproof, easily cleaned satin finish surface, resistant to oils and liquids.

TYPICAL USES	Being solvent-free, non-tainting and virtually odourless, Hy-Glaze TM WD is ideal for use in medical, animal and food environments. Typical applications include industrial kitchens and refrigerators, dairies, milking parlours, food processing areas, hospitals and schools.
SUITABLE SUBSTRATES	<i>Hy-Glaze</i> [™] <i>WD</i> may be applied direct to most substrates including plaster, render, brickwork, blockwork, plasterboard, timber, chipboard and other composite boards materials, concrete and steel.
PACKAGING	<i>Hy-Glaze[™] WD</i> is supplied in pre-measured quantities as a two part 5.0kg unit, comprising a coloured epoxy blend Part 'A' and resin Part 'B'.
COLOUR	<i>Hy-Glaze WD</i> is available in a selection of stock colours, or in a large range of BS4800 & RAL specifications, subject to minimum quantity.

COLOUR GUIDE

HyGlaze WD is available in 6 standard colours. Other colours are available on request.



The colours indicated here are approximate and should not be taken as the exact shade.

DIRECTIONS FOR USE

SURFACE PREPARATION

THOROUGH SUBSTRATE PREPARATION IS ESSENTIAL.

All loose friable or flaking material must be removed, and the surface must be clean, dry and free of dust.

Any oil or grease should be removed.

MIXING

Having fully prepared the substrate, stir the individual components before mixing together. Add Part 'A' to Part 'B' and thoroughly mix for at least 3 minutes.

For best results use a heavy duty slow speed drill with a mixing paddle.

ENSURE THOROUGH MIXING AS AN UNMIXED PRODUCT WILL RESULT IN A POOR OR NON-CURE SITUATION.

APPLICATION

Apply by brush or roller, making sure that the surface is completely covered. Particular attention should be given to any protrusions or other vulnerable areas. When finished, **DO NOT** scrape the remaining contents from the container as this will invariably include unmixed raw resin.

A second coat of *Hy-Glaze*[™] *WD* should be applied after initial curing has taken place – see 'Pot Life & Curing Times'.

POT LIFE & CURING TIMES

The pot life once mixed is approximately 45 minutes at +20°C. Initial curing takes place within 16-24 hours depending on temperature. To ensure a good intercoat chemical bond, the top coat should be applied within 16-24 hours. If this interval is exceeded, abrade the first coat to ensure intercoat adhesion. Full cure strength is reached at 7 days.

Polycote UK Centre Point • Wolseley Road Woburn Road Industrial Estate Kempston • Beds • MK42 7EF Technical Helpline: 01234 846400

APPLICATION TEMPERATURE

Normal application temperature range is between +10°C and +30°C. *Hy-Glaze*TM *WD* will cure at +5°C but curing times can be greatly extended at lower temperatures. If in doubt, please contact Polycote Technical Helpline for further advice.

COVERAGE

The coverage of Hy-GlazeTM WD is 30-40m² per 5.0kg unit, depending on the texture and porosity of the surface.

CLEANING

Tools and equipment should be cleaned whilst resin is still wet using warm soapy water.

Hands and skin should be cleaned immediately with organic hand cleaner.

SHELF LIFE & STORAGE

Shelf life in unopened containers is approximately 12 months subject to conditions of storage. Store in a cool, dry, frost-free environment away from sources of ignition.

()

r Road, npston,
rnally
AR 0.5 B 3 IR >4

HEALTH & SAFETY

Before using this product, please ensure you have received and read carefully both the Hazard Label applied to the container and the relevant Material Safety Data Sheets.

ANY QUESTIONS?

Please do not hesitate to contact us for advice regarding the use of this product or its suitability for your particular application. Our aim is to provide all the technical help you need to make an informed choice and achieve total success.

Polycote Technical Helpline 01234 846400

All reasonable care has been taken in supplying the above information. However, any figures quoted do not constitute a specification but represent typical values obtained. It is the customer's responsibility to ensure for himself that the product is fit for the intended purpose and that conditions are suitable. Any technical advice is offered in good faith, but without warranty. This is also applicable when proprietary rights and third parties are involved. In the light of the Company's policy of continual research and development, it is the customer's responsibility to ensure that the information contained herein has not been superseded.

REV: 06/17



"maintenance made easy"